


OVS VERSES



No Contest!



OWS Discharge

163 PPM



**Bag Filter Discharge With 3.0
Emulsion Conditioning Media**

156 PPM



**Discharge OX4 With
Emulsion Busting Cartridges**

None Detected

The above samples were taken from a 6 month old OWS onboard an oil tanker that has emulsified oil problems. The first sample was taken from the OWS without any of our OIL-XORB filters installed. The second sample was taken with our Bag Filter installed to condition the oil being sent to the emulsion busting cartridge filters. The final sample is the discharge from our OIL-XORB cartridge filter using the emulsion busting blend.

Lab results from Associated Laboratories. Lab request 133391. Testing method was EPA 1664 Oil & Grease.



Vigilant Marine Systems, LLC
170 N. Maple Street • Suite 104 • Corona, CA 92880
Tel: + 1 951-808-9940 • Fax: + 1 951-808-8530
email: info@vigilantmarine.com • www.vigilantmarine.com